U.S. Consumer Product Safety Commission
Office of Communications
4330 East West Highway, Bethesda, MD 20814
WWW.CDSC.QOV

Liberty Hardware Recalls Decorative Metal Wall Plates

Recall Date: March 8, 2016 Recall Number: 16-115

Liberty Hardware Recalls Decorative Metal Wall Plates Due to Shock and Fire Hazard http://www.cpsc.gov/en/Recalls/2016/Liberty-Hardware-Recalls-Decorative-Metal-Wall-Plates/

Recall Summary

Name of Product: Wall plates

Hazard: The decorative wall plates can dislodge from the backplate and short circuit the outlet, posing a risk of electrical shock or fire.

Remedy: Refund

Consumers should immediately stop using the recalled wall plates, remove them and contact Liberty Hardware Manufacturing for a full refund.

Consumer Contact: Liberty Hardware Manufacturing toll free at 844-811-4541 from 8 a.m. to 5 p.m. ET Monday through Friday or online at www.libertyhardware.com and click on "Recall Notice" for more information.

Recall Details

Photos available at http://www.cpsc.gov/en/Recalls/2016/Liberty-Hardware-Recalls-Decorative-Metal-Wall-Plates/

Units: About 374,000

Description: The recalled allen + roth Linden and Brainerd Ironton wall plates have two plates that are attached by hidden fasteners: (1) a backplate that screws into the wall like traditional wall plates, and (2) a decorative cover that snaps over the cover through use of spring clips. The recalled plates have a smooth, metallic finish and fit a variety of switch and outlet designs. The recalled decorative wall plates snap onto the backplate without the use of screws. Under the decorative plate, the backplate is stamped with the letters "LHMC."

Incidents/Injuries: The firm has received two reports of short circuits when the decorative plate dislodged from the back plate and touched an energized, partially released plug. No injuries have been reported.

Sold at: Lowe's Home Improvement stores nationwide and and online at www.dlawlesshardware.com, <a href="www.dlawlesshardwa

Importer/Distributor: Liberty Hardware Manufacturing Corp., of Winston-Salem, N.C.

Manufactured in: Vietnam and China

